


к ГОСТ 520—89 Подшипники качения. Общие технические условия

В каком месте	Должно быть
Пункт 4.17. Чертеж 16	 <p>The diagram shows a cross-section of a roller bearing assembly. A central shaft is supported by two bearings. The bearing on the right is shown with a roller and a lock washer (lock washer) secured with a screw. The lock washer is positioned to prevent axial movement of the roller. The shaft is fixed at both ends, indicated by hatching symbols.</p>

(ИУС № 10 1989 г.)